

Rossmönster Vans, LLC
501 S Francis Street
Longmont, CO, 80501
rossmonster.com



3/4/26

IMPORTANT SAFETY RECALL NOTICE

This notice applies to your vehicle VIN: **

NHTSA Recall No.:26v100

Rossmönster Recall No.: 26v100

Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Rossmönster has decided that a defect which relates to motor vehicle safety exists in certain **2023, 2024, and 2025 Baja EX and LX models** equipped with Carli extended stainless-steel front brake lines.

What is the problem?

The front brake line mounting bracket may not have been properly secured or indexed during assembly, which can cause the brake line to contact the inside sidewall of the front tire at full steering lock.

What is the safety risk?

If the brake line contacts the tire during operation, continued abrasion may damage the brake line and result in a brake fluid leak. A brake fluid leak may reduce braking performance and increase the risk of a crash.

Rossmönster Vans, LLC
501 S Francis Street
Longmont, CO, 80501
rossmonster.com



What are the warning signs?

Owners may observe one or more of the following:

- Low brake fluid level in the reservoir
- Illumination of the brake warning indicator lamp
- A soft or spongy brake pedal
- Increased stopping distance
- Visible brake fluid leakage
- Visible abrasion or wear marks near the brake line and tire area

If any of these conditions are observed, do not drive the vehicle and contact Rossmönster or an authorized service provider immediately.

What will Rossmönster do?

Rossmönster will inspect the front brake line routing and mounting bracket. The brake line bracket will be properly secured and indexed to its intended inboard position to ensure adequate tire clearance. The slip-joint will be properly crimped, and the brake line will be secured to prevent movement.

If any abrasion or damage is identified, the brake line will be replaced. This repair will be performed **free of charge**.

What should you do?

Please contact Rossmönster at [phone number] or [email address] to schedule an appointment for this recall repair. The repair is expected to take approximately [X] hours; however, your service provider may require the vehicle for a longer period depending on scheduling.

Rossmönster Vans, LLC
501 S Francis Street
Longmont, CO, 80501
rossmonster.com



Reimbursement Information

If you have already paid to have this condition corrected prior to receiving this notice, you may be eligible for reimbursement. To request reimbursement, please provide a copy of your repair receipt along with proof of payment to:

Rossmönster 501 South Francis St, Longmont, CO 80501 - Service@rossmonster.com

If You Need Assistance

If you have questions regarding this recall, please contact Rossmönster at or Service@rossmonster.com or 720-295-0623.

If you believe that Rossmönster has failed or is unable to remedy this defect without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at **1-888-327-4236 (TTY 1-800-424-9153)**, or visit www.nhtsa.gov.

What if you are a Lessor?

Federal law requires that you forward a copy of this safety recall notice to the lessee within 10 days.

What if you no longer own this vehicle?

If you no longer own the vehicle, complete the attached change of ownership card and mail it or contact customer assistance at 720-295-0623.

We apologize for any inconvenience this may cause. Your safety is our highest priority, and we appreciate your prompt attention to this matter.

Sincerely,

Rossmönster

Trenton Sweet - Ownership Experience Lead

Rossmönster Vans, LLC
501 S Francis Street
Longmont, CO, 80501
rossmonster.com

service@rossmonster.com - [\(720\) 295-0623](tel:(720)295-0623)

