

IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN:

NHTSA Recall # 26V-156

Tiffin Recall # TIF-147

March 31, 2026

Incorrect Cargo Carrying Capacity Label

Dear Tiffin Motorhome Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.



Tiffin Motorhomes has decided that certain **2025 and 2026 GH1 Motorhomes, 2025 and 2026 GT1 Motorhomes, and 2026 GH2 Motorhomes built between March 20, 2024, through March 12, 2026**, fail to conform to Federal Motor Vehicle Safety Standard No. 110, Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of 4,536 kg (10,000 lbs.) or less.

Certain motorhomes do not have the correct safety belt equipped seating capacity listed on the Occupied Cargo Carrying Capacity label, which can lead to additional passengers in the motorhome that are not secured by a seatbelt. Passengers in a motorhome that are not secured by a seatbelt can lead to injury.

Tiffin Motorhomes will replace the incorrect label with a label that correctly states the safety belt equipped seating capacity listed.

To correct this issue, we are sending owners a corrected Occupied Cargo Carrying Capacity Label to be placed in your motorhome (enclosed).

1. The yellow Cargo Carrying Capacity Label can be found on the passenger's side door panel Figure 1.
2. Remove the old label and discard.
3. Clean the passenger's side door jamb with isopropyl alcohol and place the new label as shown in Figure 2.



Owners may choose to take the motorhome to a service center or dealer of your choice to have the enclosed label installed. Please allow 10 minutes to have the label installed. This work will be completed at no charge to you, the owner.

If you are using a service center that is not a Tiffin Motorhomes authorized repair facility, please make sure that they contact Tiffin Motorhomes for the required parts, instructions and time allowed for the repair. Tiffin Motorhomes will not pay over the allowed time unless the repair facility receives prior authorization. For authorization, contact Tiffin Motorhomes at 256-356-0261 or service@tiffinmotorhomes.com.

You may be liable for any progressive damage that results from your failure to complete the recall within a reasonable time after receiving notification.

If owners have paid to have this repair completed, please send a copy of the invoice, that was paid by the owner to Tiffin Motorhomes at the following address: Tiffin Motorhomes, Attn: Recalls, 105 2nd Street NW, Red Bay AL 35582 or by email to service@tiffinmotorhomes.com. Please make sure the invoice lists who paid for the repair, the VIN of the motorhome and the date the repair was completed.

If you do not own the vehicle that corresponds to the vehicle identification number which appears on this Recall Notification, please return the notification to the Tiffin Motorhomes Recall Department with any information you can furnish that will assist us in locating the present owner. You may also send an email to recalls@tiffinmotorhomes.com.

If you are unable to have the defect remedied without charge and within a reasonable time after you tender the vehicle for repair, please contact the Tiffin Warranty Department, at 1-256-356-8661, 8:00 a.m. to 3:30 p.m., Central Time. You may also wish to notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or phone 1-888-327-4236 (TTY: 1-888-275-9171): or go to <http://www.safercar.gov>.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

Tiffin Motorhomes Compliance Department