

Recall Campaign Bulletin



April 2026

TO: ALL MERCEDES-BENZ DEALERS

CAMPAIGN NO.	2026040002
CAMPAIGN DESC.	26P9190320
NHTSA ID	26V172
SUBJECT	Replace Rear Center Seat Belt
MODEL(S)	GLC (254 platform)
MODEL YEAR(S)	2026
CAMPAIGN POPULATION	20

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

Order No. P-RC-2026040002

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Model(s): 254

Primary Parts Information

Qty.	Part Name	Part Number
As required (1)	Seat belt (model 254.3)*	A 254 860 36 01 **
As required (1)	Seat belt (model 254.6)*	A 254 860 23 00 **
As required (1)	Head restraint guide, rear seat backrest, left, right*	A 206 970 23 00 **
As required (1)	Head restraint guide, rear seat backrest, left, left*	A 206 970 22 00 **


* The replacement parts must be determined according to the equipment variant for the vehicle identification number (VIN/FIN) via XENTRY Parts Information System.

** The supplementary color code must be specified according to the vehicle identification number via the XENTRY Parts Information System.

 Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Check/Test procedure

1. Check part number of belt tongue (Figure 1, 1) on the center seat belt in rear passenger compartment.

**Figure 1**

- a. If the installed belt tongue (Figure 1, 1) does **not** have **part number A 254 860 36 01 (model 254.3) or A 254 860 23 00 (model 254.6)**: Perform **Work Procedure**.
- b. If the installed belt tongue (Figure 1, 1) has **part number A 254 860 36 01 (model 254.3) or A 254 860 23 00 (model 254.6)**: No further action required.

Model(s): 254

Work Procedure

1. Replace center seat belt in rear passenger compartment.

 For basic information, see AR91.40-P-0683WT.

 **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
91 903 20	11-0089	Check center rear seat belt	0.1
	11-0090	Replace center rear passenger compartment seat belt (after check) Includes: Remove/install respective head restraint in rear passenger compartment, remove/install respective head restraint guides of seat backrest in rear passenger compartment, remove/install rear seat cushion padding, remove/install folding left rear seat backrest and remove/install left rear seat backrest outer cover.	0.9

 **Note:** Always check XENTRY Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.