

Recall Campaign Bulletin



May 2026

Revision A June 26, 2026

TO: ALL MERCEDES-BENZ DEALERS

CAMPAIGN NO.	2026040009
CAMPAIGN DESC.	26P9193119
NHTSA ID	26V199
SUBJECT	Replace Front Passenger Airbag
MODEL(S)	GLE and GLS (167 platform)
MODEL YEAR(S)	2026
CAMPAIGN POPULATION	888

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

Revision Note(s):

- Updated Warranty Information Table

Order No. P-RC-2026040009

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Primary Parts Information

Qty.	Part Name	Part Number
1	Front Passenger Airbag	A 167 860 78 01

** The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts process in the Xentry Portal.*

 Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list, but may be claimed as needed. The required small parts are taken into account in the budgeting.

Work Procedure

1. Replace passenger front airbag.

 For basic information, see AR91.60-P-0664ME.

Warranty Information

 **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
91 931 19	11-1582	Replace front passenger airbag Includes: Disconnect/connect battery ground line, performing quick test	1.1
	11-1592	Extra work for replacing front passenger airbag on vehicle with code 224 rear individual seat. INCLUDES: Remove/install center console in rear passenger compartment	ZM-Not to exceed 1.7hr

 **Note:** Always check XENTRY Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.