



NHTSA Safety Recall 26v-277

TC Safety Recall 2026-215

Claim Preparation & Repair Instructions

Please complete a warranty claim pre-authorization request using the following codes & labor times:

LABOR:	Operation Code:	M910060
	Fault Code:	Recall
	Administrative Allowance:	0.1 hrs. per unit
	Repair Time:	0.2 hrs. per unit
	Tools:	13mm Impact Socket Std Length 3/8" Extension Bitt Torque wrench capable of ft lbs

PRE-AUTH:

- No photos are required for payment.
- No parts are required or will be reimbursed for claim.
- No shop supplies will be reimbursed for claim.

FILING:

Promptly submit all pre-authorizations/claims through our Dealer Portal. If you have any questions or need assistance, please call our Technical Service Team at 888-825-2820.

REPAIR INSTRUCTIONS:

- 1) Run both driver and passenger seats all the way forward
- 2) Torque the 1st 2 bolts closest to the door to 35 ft lbs
- 3) Pivot seat ¼ of a turn towards the door to expose the 2 bolts on the inside of the seat
- 4) Enter the motorhome through the entry door to easily access the inside bolts
- 5) Torque the inside 2 bolts to 35 ft lbs
- 6) Repair Complete

