

 Tesla, Inc. Service Bulletin		<i>Inspect B-Pillar for Certification Label</i>	
SB-26-19-002 May 20, 2026			
Classification		Section/Group	Mobile Service
Recall Bulletin		19 - Labels	Can Perform (where permitted)
			All
Model	Model Year	Country/Region	Build Location
Model Y	2025–2026	North America	Fremont, Giga Texas
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.			

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Model Y vehicles may not have a certification label on the driver's side B-pillar as required by 49 CFR Part 567.

Correction

Inspect the vehicle to confirm that the vehicle has a certification label. If the label is not present, affix the label.

Correction Description	Correction	Time
Inspect B-Pillar for Certification Label; Label Already Installed	S012619002	0.06
Inspect B-Pillar for Certification Label; Install Label	S022619002	0.06

	Part Number	Description	Quantity
Parts Required	1462927-00-C	LABEL - MFG CERTIFICATION	1
This part number is current at the time of publication. Use the revision listed or later, unless otherwise specified in the Parts Catalog.			
Shop Supplies		Isopropyl alcohol wipes	

Procedure

1. Open the driver's side door and verify that the certification label is present (Figure 1).
 - If the certification label is present, discontinue this procedure and use correction code S012619002.
 - If the certification label is not present, continue to the next step.



Figure 1 –Certification Label Location (LHD vehicle)

2. Clean the certification label location with an isopropyl alcohol wipe. Allow the area to dry for at least one minute.
3. Inspect the new label to verify that it matches the vehicle VIN (Figures 2 and 3).




Figure 2 – VIN location on label



Figure 3 – VIN location on vehicle

4. Affix the certification label onto the driver's side B-pillar (Figure 4). Make sure that it is straight and free of wrinkles. Use correction code S022619002.



Figure 4 – Label installed on vehicle