



Foretravel Service Bulletin

Airxcel Vent Fan Recall Notification
26V-464

Foretravel Dealer:

Introduction: Foretravel has determined on the model year 2027, Foretravel Realm FS605P vehicles. Equipped with Airxcel Vent Fan fail to conform to Federal Motor Vehicle Safety Standard.

Units Affected: Production build #'s 9316, 9317 and 9318.

Please Note: Foretravel Motorcoach has 3 vehicles involved with this recall.

Inspection: A visual inspection of the printed circuit board (PCB) build date installed in the fan assembly contains a safety defect that can result in overheating of the PCB that could result in a fire.

Action: The recall remedy is to inspect for correct build date. See attached Airxcel Service Bulletin.

Solution: Replace Printed Circuit Board if the affected PCBs were built between December 15, 2025 and June 17, 2026.

Labor: .25 for inspection only
.50 for replacement Printed Circuit Board

Note: Inspection photos of the PCB per the attached Bulletin can also be sent to Foretravel to determine if the recall repair will be required. The PCB inspection photos can be sent to Noreply@foretravel.com or 800-955-6226 ext. 187.