

**Recall 294 [NHTSA Recall # 26V-068] In-Vehicle Message**

Safety Recall 294: Your IONIQ 5 may have a battery system assembly installed with an insufficiently tightened retention bolt. Please contact Hyundai customer care as soon as possible at 844-462-5557 to schedule the repair. A complimentary loaner will be provided.