



Head Unit Notification:

Safety Recall 305

Your IONIQ 5 is affected by recall 305 involving the high voltage battery. Until the remedy is completed, please follow these precautions to reduce the risk of a potential fire: park your vehicle outside and away from structures and limit the maximum charge to 80%.

