



Head Unit Notification:

Safety Recall 306

Your vehicle is affected by a safety recall involving the second-row center seat belt buckle. In certain crash conditions, the seat belt buckle may not perform as intended, which could increase the risk of injury. Hyundai recommends that the second-row center seating position not be occupied until the recall repair is available and has been completed. We will notify you as soon as a remedy becomes available.

