

## D095 – PANORAMIC ROOF SIDE FINISHERS SAFETY RECALL



AFFECTED MODELS	23-26MY Range Rover and Range Rover Sport
VOLUME AFFECTED	173 US 14 CAN
CONCERN	<p>A concern has been identified on certain vehicles where the adhesion process used to re-attach the panoramic roof side finishers during vehicle quality rework operations in the assembly plant may not have been sufficient.</p> <p>An inadequately adhered panoramic roof side finisher could, over time, come partially or completely loose. This could result in distractions to the driver or other road users or, in the event of complete detachment, harm to other road users, particularly pedestrians or two-wheeled vehicles, and increase the risk of injury or a crash. Repair process is being developed.</p>
REPAIR TIME	TBC
CAMPAIGN LAUNCH	Retailers were notified via recall administration bulletin D095ADM1 on March 5th, 2026. Repair bulletin launch TBC
NOTES	<p>Please review the content in the administration bulletin and observe all instructions relating to unsold vehicles in retailer inventory.</p> <p>Clients will be notified by mail on or before April 17th, 2026</p>