



**2ND/3RD ROW POWER SEAT
ASSEMBLIES
P37 CAMPAIGN**

VIN Validation

Input your Vehicle Identification Number to verify if your vehicle is affected by this recall.

VIN (Vehicle Identification Number)

VALIDATE

[What is a VIN?](#)

The 2nd and 3rd row power seats in your 2026 Palisade or 2026 Palisade Hybrid may not detect contact with an occupant or object as intended in certain situations. In the interim, Hyundai advises using caution when operating power-folding seats, ensuring that no person or object is in the seat or seat-folding area during operation, and supervising children seated in the 2nd and 3rd rows. Customers should also avoid pressing the 2nd row one-touch tilt and slide (walk-in function) button during 3rd row entry or exit. To avoid unintended activation of the power seat switch panel, use care when stowing cargo, and be aware that the cargo-area switch panel may be accessible to 3rd row occupants.

We apologize for any inconvenience and appreciate your prompt attention to this matter. Should you have questions concerning this issue, please do not hesitate to contact us 1-855-371-9460.

Affected Vehicles

Certain 2026 Palisade Limited
Certain 2026 Palisade Calligraphy
Certain 2026 Palisade Hybrid Limited
Certain 2026 Palisade Hybrid Calligraphy



Hyundai is a registered trademark of Hyundai Motor Company. All rights reserved. © 2026 Hyundai Motor America

[Privacy Policy](#) | [Legal Notice](#)