



Toyota Motor North America, Inc.
Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

September 2, 2026

NONCOMPLIANCE INFORMATION REPORT

1. Vehicle Manufacturer Name:

Toyota Motor Corporation [“TMC”]
1, Toyota-cho, Toyota-city, Aichi-pref., 471-8571, Japan

Toyota Motor Manufacturing Guanajuato [“TMMGT”]
México 45D, 38195 San Pedro Tenango, Gto., Mexico

Toyota Motor Manufacturing, Texas, [“TMMTX”]
1 Lone Star Pass, San Antonio, TX 78264

Affiliated U.S. Sales Company:

Toyota Motor North America, Inc. [“TMNA”]
6565 Headquarters Drive, Plano, TX 75024

2. Identification of Involved Vehicles and Affected Components:

Based on production records, we have determined the involved vehicle population to be the vehicles listed in the table below.

Make/Car Line	Model Year	Manufacturer	Production Period
Toyota / 4Runner	2026	TMC	January 20, 2026 through January 22, 2026

Toyota / 4Runner HV	2026	TMC	November 03, 2025 through March 13, 2026
Toyota / RAV4 HV	2026	TMC	December 08, 2025 through December 10, 2025
Toyota / Tacoma HV	2024	TMMGT	July 26, 2024 through October 24, 2024
Toyota / Tundra	2025	TMMTX	November 06, 2024 through March 28, 2025
Toyota / Tundra HV	2025	TMMTX	December 12, 2024 through December 12, 2024

Part Number	Part Name	Component Description
PT990-34220	Accessory Weight Rating Label	Accessory Weight Rating Label

Note: (1) Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S.

(2) Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this manual data entry error.

3. Total Number of Vehicles Potentially Involved:

4Runner : 2
4Runner HV : 22
RAV4 HV : 3
Tacoma HV : 92
Tundra : 15
Tundra HV : 1
Total : 135

4. Percentage of Vehicles Estimated to Actually Contain the Noncompliance:

100%

5. Description of Noncompliance:

Due to manual data entry errors, specific accessory weight values were incorrect in a Toyota system. Thus, the total weight of the accessories installed in the subject vehicles by Toyota were miscalculated. In these vehicles, this resulted in a load carrying capacity modification label with an understated reduction in load carrying capacity greater than one percent of the actual added weight. As a result, the subject vehicles do not meet the requirements of FMVSS No. 110, paragraph S10.2. If a driver follows the understated label and loads the vehicle to the indicated load carrying capacity, it is possible that the vehicle will be loaded beyond its load carrying capacity, increasing the risk of a crash.

6. Test Results and Other Information:

From March through June 2026, as part of an internal audit activity, Toyota analyzed accessory parts catalog information and identified weight discrepancies in 8 accessories due to manual entry errors. For the 8 accessories, Toyota identified the discrepancy between the weight on the actual part drawing and the weight used in the system. From July to August 2026, Toyota conducted a VIN-by-VIN review on vehicles that could have received one or more of the affected parts to compare the weights that were used to print the labels to the weight of the total accessories installed by Toyota. On August 27, 2026, Toyota decided that the subject vehicles do not meet the requirement of FMVSS No. 110 paragraphs S10.2.

7. Description of Corrective Repair Action:

All known owners of the involved vehicles will be notified to return their vehicles to a Toyota dealer. Dealers will replace the load carrying capacity modification label with an updated one at no cost to owners.

Reimbursement Plan for pre-notification remedies

As the owner notification letters will be mailed out well within the active period of the Toyota New Vehicle Limited Warranty ("Warranty"), all involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's Warranty.

8. Recall Schedule:

Notifications to owners of the affected vehicles will occur by November 1, 2026. A copy of the draft owner notification will be submitted as soon as it is available.

9. Distributor/Dealer Notification Schedule:

Notifications to distributors/dealers will be sent on September 2, 2026. Copies of dealer communications will be submitted as they are issued.

10. Manufacturer's Campaign Number:

Remedy: 26TA18