



INFOTAINMENT MESSAGING FOR OVER-THE-AIR UPDATE

RECALL ID Kia: SC361 / NHTSA: 26V046

INSTALLATION Once the over-the-air (OTA) software has been automatically downloaded and the background update is finished, the software update will be available to install.

Pop-up Screen Text after Engine is turned off:

When you select [Update Now], the screen will turn off and the navigation update will start. Navigation will turn off automatically after the update.

- Use Auto-Install Updates [Check box]
- Update Now [selectable]
- Details [selectable]
- Later [selectable]

DETAILS SCREEN TEXT Use of all functions, including sound, is limited during the update.

- Total Update Time: 10 Minutes

UPDATE DETAILS Important OTA Software Update
Software Version: AP: CP12_M.AP.HMC.ALL.0000.V018.101.250904,
CP12_M.AP.KMC.ALL.0000.V019.127.250903 (subject to change)
MCU: CP12_M.MCU.KA4.ALL.0000.V018.102.250609,
CP12_M.MCU.KMC.ALL.0000.V019.132.250526 (subject to change)

This important update is to remedy the instrument cluster software which may become temporarily blank while driving, resulting in the driver's inability to see certain telltales and indicators required by Federal Motor Vehicle Safety Standard (FMVSS). In its current state, your vehicle does not comply with the visibility and illumination requirements of FMVSS 101, §§ S5.1.2 and 5.3.1(b) and FMVSS 138, § S4.2, thereby increasing the risk of your vehicle being in a crash.

If the OTA software update is unsuccessful, you are advised to bring your vehicle to a Kia dealer to complete Recall SC361.

- Previous [selectable]
- Start Update [selectable]
- Later [selectable]

SCREEN AFTER START Updating...

UPDATE/UPDATE NOW SELECTION The update will continue even when the vehicle is turned off. During the update, all features including the rear camera and audio are restricted.

- AFTER UPDATE** What's New & QR Code Pop-Up Screen text after the update:
- What's New
 - For more information on the Infotainment System Update, press the [Details] button.
 - Details [selectable]
 - Close [selectable]
- If Details is selected, it directs to the What's New > Vehicle System Update page.

WHAT'S NEW DETAILS Important OTA Software Update
SCREEN Software Version: AP: CP12_M.AP.HMC.ALL.0000.V018.101.250904,
CP12_M.AP.KMC.ALL.0000.V019.127.250903 (subject to change)
MCU: CP12_M.MCU.KA4.ALL.0000.V018.102.250609,
CP12_M.MCU.KMC.ALL.0000.V019.132.250526 (subject to change)

This important update is to remedy the instrument cluster software which may become temporarily blank while driving, resulting in the driver's inability to see certain telltales and indicators required by Federal Motor Vehicle Safety Standard (FMVSS). In its current state, your vehicle does not comply with the visibility and illumination requirements of FMVSS 101, §§ S5.1.2 and 5.3.1(b) and FMVSS 138, § S4.2, thereby increasing the risk of your vehicle being in a crash.

If the OTA software update is unsuccessful, you are advised to bring your vehicle to a Kia dealer to complete Recall SC361

QR CODE APPEARS ON What's New QR code directs to a general information website referenced in the document,
THE SCREEN "KIA Connect App Messaging for OTA".