

PAGES 1 TO 14 ARE PROTECTED  
BY COPYRIGHT AND HAVE BEEN  
PURPOSELY OMITTED

## OWNER'S LETTER

Dear Infiniti G35 Owner:

Infiniti is committed to providing the highest levels of product quality and customer satisfaction. With that in mind, we want to bring to your attention important information regarding the clutch hydraulic system in your 2007 G35.

### REASON FOR SERVICE ACTION

Infiniti has discovered that on certain 2007 G35 vehicles equipped with the 6-speed manual transmission, the clutch slave cylinder assembly may not have been manufactured properly. This could result in the operating force of the clutch pedal becoming light, and in some cases, could result in improper clutch operation.

### WHAT INFINITI WILL DO

To assure your continued satisfaction in your G35, your Infiniti retailer can replace the clutch slave cylinder assembly with a new improved part **free of charge for parts or labor**.

### WHAT YOU SHOULD DO

Please contact your Infiniti retailer at your earliest convenience in order to arrange an appointment. This free service should take about three hours to complete, but your Infiniti retailer may require your vehicle for a longer period of time based upon the workshop schedule. **To ensure the least inconvenience for you, it is important that you have an appointment before bringing your vehicle to the dealer for service.**

Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Infiniti retailer.

If the retailer fails, or is unable to complete the modifications free of charge, you may contact the National Consumer Affairs Office, Infiniti Division, Nissan North America, Inc. at P.O. Box 685003 Franklin, TN 37068-5003. The toll free number is 1-800-662-6200.

Thank you for providing us this opportunity to ensure your on-going satisfaction with your Infiniti G35.

