

HINO Parts Technical Bulletin (PTB)

Release Date: March 10th 2008 Bulletin # PTB 03-08 Affected Years: 2005 - 2008

Affected Models: Conventional, All Models

Subject: Spring Assemblies

The description in the HINO EPC for Spring assemblies on all Hino Conventional Trucks model years 2005-2008 is confusing in some instances. To help clarify the description, please refer to the information below.



U.S. Vendors identify this spring as a 2 leaf spring assembly. The HINO EPC identifies it as 3 leaves. (*Hino considers the shock mounting bracket a leaf*)



U.S. Vendors identify this spring as a 3 leaf spring assembly. The HINO EPC identifies it as 4 leaves. (*Hino considers the shock mounting bracket a leaf*)

When identifying these spring assemblies in the EPC please refer to this bulletin for clarification on the description. The HINO EPC will continue to identify the spring assemblies in this manner.

If you have any questions please contact Hino Customer Service at 866-372-4466.

Sincerely,
Your Hino Parts Team