
| | |
|------------------|----------|
| Reference | SSM36987 |
|------------------|----------|

| | |
|---------------|------------|
| Models | LR2 / L359 |
|---------------|------------|

| | |
|--------------|---|
| Title | Freelander 2 / LR2 Front Grille Black Spot Repair Procedure |
|--------------|---|

| | |
|-----------------|------|
| Category | Body |
|-----------------|------|

| | |
|----------------------|----------------------|
| Last modified | 10-Jan-2008 00:00:00 |
|----------------------|----------------------|

| | |
|----------------|---------------------|
| Symptom | 106000 Paint/Finish |
|----------------|---------------------|

| | |
|--------------------|--|
| Attachments | Cleaners.pdf (Cleaners.pdf) D800.pdf (D800.pdf) Deltron Basecoat.pdf (Deltron Basecoat.pdf) Titan Silver.doc (Titan Silver.doc) |
|--------------------|--|

| | |
|----------------|---|
| Content | <p>Should a vehicle have Black Spots identified on the Front Grille Please carry out the following repair procedure.</p> <p>Remove front Bumper from vehicle.</p> <p>Remove the Land Rover badge / decal</p> <p>Mask Front Bumper Grille leaving Silver area exposed.</p> <p>Preparation Cleaning Prepare area to be painted using Gold Scotch pad and clean using D8401 cleaner as per attached Cleaner.pdf</p> <p>Application of Basecoat Mix Titan Silver as per attached formulation. Apply colour in two stages as per attached Deltron Basecoat.pdf</p> <p>Application of Clearcoat Laquer Apply 2 coats of D800 matted to the 'matt' level. Use D841 hardener and D807 thinner as per D800.pdf</p> <p>Once dry, polish to finish and refit bumper to vehicle, fit Badge</p> <p>Note Du Pont materials may also be used but must meet the specification on attached files</p> <p>Repair SRO 79.HBC</p> |
|----------------|---|

