

Reference	SSM41158
Models	XF / X250
Title	Rust Spots on Rear Bumper Upper Surface
Category	Body
Last modified	13-May-2009 00:00:00
Symptom	106000 Paint/Finish
Attachments	boot seal flush for rust on bumper.pdf
Content	<u>Issue:</u> Rust spots may be noticed on the rear bumper. <u>Cause:</u> Particles of metal remaining from boot seal manufacturing process, exiting the boot aperture seal. <u>Action:</u> Clean bumper with spirit based wipe suitable for painted surfaces. Find hole on vertical section of seal. Insert suitable water hose nozzle. Flush seal with water. Squeeze seal to remove all water. Repeat for other side of vehicle. Refer to .ppt file for pictorial guidance.