

| | |
|----------------------|--|
| Reference | SSM41158 |
| Models | XF / X250 |
| Title | Rust Spots on Rear Bumper Upper Surface |
| Category | Body |
| Last modified | 13-May-2009 00:00:00 |
| Symptom | 106000 Paint/Finish |
| Attachments | boot seal flush for rust on bumper.pdf |
| Content | <p><u>Issue:</u> Rust spots may be noticed on the rear bumper.</p> <p><u>Cause:</u> Particles of metal remaining from boot seal manufacturing process, exiting the boot aperture seal.</p> <p><u>Action:</u> Clean bumper with spirit based wipe suitable for painted surfaces. Find hole on vertical section of seal. Insert suitable water hose nozzle. Flush seal with water. Squeeze seal to remove all water. Repeat for other side of vehicle.</p> <p>Refer to .ppt file for pictorial guidance.</p> |

