
Reference	SSM42872
Models	XF / X250 XK / X150
Title	Headlamps - Diagnostics and Testing
Category	Electrical
Last modified	27-Nov-2009 00:00:00
Symptom	201000 Lighting Systems
Content	<p><u>Issue:</u> Jaguar are continuing to see no fault found warranty returns on headlamps and associated control modules</p> <p><u>Cause:</u> Incorrect diagnosis.</p> <p><u>Action:</u> The diagnostics and testing section in the workshop manuals for XK and XF headlamps has been updated to aid with diagnosis of headlamp faults reported by the customer.</p> <p>Prior to replacing a headlamp or headlamp control module, please refer to the headlamp diagnostics and testing in section 417-01 of the workshop manual."</p>