



A **PACCAR** COMPANY

Date

Customer Name

Customer Address

Subject: Kenworth campaign E010 – C1033
Expiration date June 22, 2012

Dear Kenworth Customer,

Kenworth has determined that certain vehicles equipped with PACCAR PX engines, manufactured between October 23, 2009 and July 1, 2010, will benefit from recalibration of the Engine Control Module (ECM) and of the aftertreatment Diesel Exhaust Fluid (DEF) controller. Updates may also include replacing various components of the aftertreatment system (to be determined by the authorized repair shop). The vehicle(s) identified by VIN on this letter is (are) subject to this campaign repair.

Left uncorrected, it is possible that your vehicle will display erroneous fault codes, check engine lamp warnings, premature DEF filter plugging, possible DEF leaks or other component failure.

We encourage you to schedule for repairs as soon as possible. Please contact your authorized PACCAR Engine dealer or Cummins Distributor for an appointment. Repairs will take approximately four hours and will be performed at no cost to you if completed by June 22, 2012.

If contacting a PACCAR dealer to perform this work, please refer to campaign E010. If contacting a Cummins Distributor, refer to campaign C1033.

We apologize for the inconvenience this may cause and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Director, Quality Services
Kenworth Truck Company