



Tech Tips

TT 87-11-01

Date: March 18, 2011

2011-2013 Jetta (except Hybrid and GLI with Climatronic),
2012-2013 Beetle – A/C Control Module Basic Settings

May 31, 2013: Update to applicability.

After A/C control module J301 is replaced, fault 00898-005 “Activation A/C Compressor No or Incorrect Basic Settings” may be stored. GFF test plan does not perform Activation A/C Compressor Basic Setting. To perform basic setting and resolve this fault, follow steps below:

- Begin with key OFF.
- Set the blower on position 1 or 2.
- Start the engine.
- Press and hold the rear defogger and a/c buttons at the same time.
- Hold the buttons for 5-7 seconds until the rear defogger, A/C, and recirculation buttons are illuminated.
- Switch the engine OFF.
- Restart the vehicle and recheck all functions before returning the vehicle to the customer.