



February 04, 2010

Dear Blue Bird Owner,

You will find enclosed a copy of Service Bulletin S10RA regarding the body control module on your 2010 model year Blue Bird All American model bus(es).

If the serial number of the body control module on your bus(es) is found on the list provided in the attached Service Bulletin S10RA, it will need to be replaced. Instructions for locating the serial number on the body control module and, if necessary, for replacing the body control module are provided in Service Bulletin S10RA. A copy is attached.

Your buses affected by Service Bulletin S10RA are identified by Blue Bird body number on the enclosed cover sheet.

Time allowed for inspecting and identifying the body control module serial number is 0.25 hrs (15 minutes) per bus.

Time required to replace the body control module, if necessary, is 0.25 hrs (15 minutes) per bus.

You will need to contact your Blue Bird dealer to obtain replacement body control modules.

You may contact your Blue Bird dealer to arrange to have Service Bulletin S10RA performed. Or, if you prefer, you may perform the inspection and /or replacement yourself or have a qualified repair facility convenient to you perform Service Bulletin S10RA. A qualified technician should perform this procedure.

Service Bulletin S10RA expires one (1) year from date of issue.

Should you have any questions concerning this bulletin, please contact your Blue Bird dealer.

Sincerely,



Bill Coleman
Blue Bird Corporation
478-822-2242
bill.coleman@blue-bird.com



Body Control Module

MODELS AFFECTED: 2010 D3FE and D3RE All American

ISSUE

Affected buses, under certain conditions may exhibit any or all of the following symptoms related to the Body Control Module: Blown number 5 fuse. Windshield wipers sweep when the Ignition Switch is on and wiper switch is off. Stop arm activates when the Ignition Switch is switched on.

CORRECTIVE ACTION

This Bulletin provides the list of serial numbers for Body Control Modules which must be replaced.


PROCEDURE READ THESE INSTRUCTIONS COMPLETELY BEFORE STARTING THE PROCEDURE

WARNING Always follow all federal, state, local, and shop safety standards and use proper safety equipment when performing this procedure.

1 Secure the vehicle and prepare it for access to the needed areas:

1.1 Park vehicle on level surface. Apply the parking brake. Remove key and chock wheels. Disconnect the negative battery cables; then disconnect the positive battery cables.

1.2 Open the outside side electrical compartment compartment and locate the Body Control Module.



Body Control Module



2 Locate the Body Control Module serial number at the bottom left corner of the module. If necessary, remove the mounting screws and carefully shift the module to gain view of the serial number. Compare the serial number to the list on page 2.

- If the serial number is not listed, the module is not one of the affected units, and no further action is required. Remount the Body Control Module if it was moved, and return the bus to normal service.
- If the serial number is listed on page 2, proceed with step 3.

3 Replace the Body Control Module, as follows:

3.1 Disconnect the harness plugs from the module. Remove the top two mounting screws, and loosen the bottom two mounting screws. Remove the module.

3.2 Refer to the list on page 2 to determine whether the replacement is 10001559 or 10002011. Place the new module over the bottom two mounting screws. Reinstall the two upper mounting screws. Tighten the four screws. Connect the harness connectors.

The procedure is complete, and the bus may be returned to normal service.



Serial Numbers for Modules Labeled CV-ICM-1715-01

Body Control Modules with these serial numbers must be replaced with Blue Bird part number 10001559:

02090795	02090824	21091224
02090796	04090470	21091225
02090797	04090471	21091226
02090798	04090472	21091228
02090799	04090473	21091229
02090800	04090474	21091230
02090801	04090475	21091231
02090802	04090476	21091233
02090803	04090477	21091234
02090804	04090478	21091235
02090805	04090479	21091236
02090806	04090480	21091237
02090807	04090481	21091238
02090808	04090482	21091239
02090809	04090483	21091240
02090810	04090484	37080356
02090811	04090485	37080357
02090812	04090486	46080393
02090813	04090487	46080394
02090814	04090488	46080964
02090815	04090489	46080965
02090816	04090490	46080966
02090817	21091217	46080967
02090818	21091218	46080968
02090819	21091219	46080969
02090820	21091220	46080971
02090821	21091221	46080973
02090822	21091222	46080976
02090823	21091223	46080980

Serial Numbers for Modules Labeled CV-ICM-1715-02

Body Control Modules with these serial numbers must be replaced with Blue Bird part number 10002011:

45080122	50081051	50081054
50081049	50081052	
50081050	50081053	

PARTS

PART NUMBER	QUANTITY	DESCRIPTION
10001559	1	Module, Body Control CV-ICM-1715-01
10002011	1	Module, Body Control CV-ICM-1715-02