

**IMPORTANT: PRODUCT ADVISORY ENCLOSED  
PLEASE OPEN IMMEDIATELY**

PLEASE DELIVER TO REGISTERED OWNER

VEHICLE  
IDENTIFICATION ► XXXXXXXXXXXXXXXXXXXX  
NUMBER



\*\*\*\*\*AUTO\*\*SCH 3-DIGIT 907





**ACURA**

AUTOMOBILE DIVISION  
American Honda Motor Co., Inc.  
1919 Torrance Blvd., P.O. Box 2215  
Torrance, CA 90509-9870

April 2013

Dear Acura 2009 TSX Owner:

Our records indicate that an important PRODUCT UPDATE may not have been completed on your vehicle. On some 2009 TSX vehicles, a manufacturing problem with the windshield side trim may allow the side trim to come loose.

Please immediately contact any authorized Acura dealer to schedule a service appointment for your vehicle. The update should be completed even if your vehicle is not experiencing a problem. This work will be done free of charge. If you need assistance locating a dealer, contact Acura Client Relations. You may also find this information at [www.Acura.com](http://www.Acura.com).

We apologize for any inconvenience this update may cause you. We are taking this action in the interest of your continued satisfaction with your Acura vehicle.

Sincerely,

**American Honda Motor Co., Inc.**  
**Acura Automobile Division**

**NOTICE: If this is a leased vehicle, please forward this notice to the lessee.**

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #12-018

S27



**ACURA**

AUTOMOBILE DIVISION

American Honda Motor Co., Inc.  
1919 Torrance Blvd., P.O. Box 2215  
Torrance, CA 90509-9870

Abril del 2013

Estimado propietario de un vehículo Acura TSX 2009:

Nuestros registros indican que no se ha completado una ACTUALIZACIÓN DE PRODUCTO importante en su vehículo. En algunos vehículos TSX 2009, un problema de fabricación con la moldura lateral del parabrisas puede provocar que la moldura lateral se suelte.

Por favor comuníquese inmediatamente con cualquier concesionario autorizado Acura para programar una cita de servicio para su vehículo. La actualización debe completarse aunque su vehículo no esté experimentando un problema. Este trabajo se realizará sin costo alguno. Si necesita ayuda para ubicar un concesionario, comuníquese con Relaciones con el cliente Acura. Usted también puede encontrar esta información en [www.Acura.com](http://www.Acura.com).

Le pedimos disculpas por cualquier inconveniente que esta actualización pudiera causarle. Nosotros estamos tomando esta acción en el interés de su satisfacción continua con su vehículo Acura.

Atentamente,

**American Honda Motor Co., Inc.**  
**División Automotriz de Acura**

**AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.**

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #12-018 S27