



Service Bulletin

File in Section: -

Bulletin No.: PIC5230A

Date: December, 2012

PRELIMINARY INFORMATION

Subject: Performance Exhaust Part Number When Used With Accessory Ground Effects

Models: 2010 - 2013 Chevrolet Camaro

This PI was superseded to update model years. Please discard PIC5230.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

When adding the GM Accessory Performance Exhaust to a vehicle with GM Accessory Ground Effects, a specific exhaust kit part number is required. This exhaust part number will NOT require the exhaust tips to be cut as noted in the ground effect instructions.

Recommendation/Instructions

GM Performance Exhaust does NOT include chrome tips. Therefore, there is no need to cut the exhaust system as stated in the installation instructions.

There are different Performance Exhaust part numbers available - depending on the vehicle's engines. The GM Performance Exhaust part numbers are available in the Accessory Catalog.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.