



Service Bulletin

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Red Park Brake Indicator Remains Illuminated In IPC After Ignition Is Off

Models: 2013 Cadillac ATS
with Electronic Parking Brake (RPO J77)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may notice that after setting the Parking Brake and turning off the ignition that the Park Brake indicator remains on.

Recommendation/Instructions

Note: Do NOT replace parts for this condition.

This is normal operation and does not require any repair. If the Park Brake is applied, this indicator could stay on as little as 20 seconds or as long as the serial data bus remains Active.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION