

# Technical Service Bulletin



## 02 Rattle noise from rear of transmission at idle.

02 12 01 2031910/1 November 28, 2012.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
R8, R8- GT R8 Spyder	2008-12	All	All

## Condition

Customer may report a rattle noise from rear of transmission at idle. On manual vehicles, noise may change when clutch is depressed.

## Technical Background

The R8 is not equipped with a dual mass flywheel therefore the engine vibrations go directly into the gearbox. The gears which are not engaged will vibrate and cause a rattling noise. This noise will not affect performance of the vehicle.



**Tip:** Replacing the transmission will not change this condition.

## Production Solution

Not applicable.

## Service

Do not perform any repairs. Any repairs for this concern may be denied. Explain the technical background to the customer and inform them this is normal.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

# Technical Service Bulletin

---



## Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.