

> Constellation  
Heritage  
> 4700 Models

> 4800 Models  
> 4900 Models

> 5900 Models  
> 6900 Models

**Western Star  
Service Bulletin**

## General Information

If a vehicle that was decked during transport has a crank/no start condition, prime the fuel system following the instructions in the engine manufacturer's service manual. Refer to the Detroit Diesel or Cummins service literature for proper servicing procedures and equipment.

NOTE: This bulletin does not apply to Cummins ISC, ISL, and ISX engines as they have an electric priming pump.

## Warranty

This bulletin is informational only. Warranty does not apply.