



SUBJECT

N55 Engine: DME FC 160502 Crankcase Ventilation Heater Activation

MODEL

F10

F30

Produced from 7/2012 to present

SITUATION

The Service Engine Soon lamp is **NOT** illuminated. When diagnosing the vehicle for a customer complaint, the following fault is stored in the DME fault memory.

FC 160502 Crankcase ventilation heater, activation: short circuit to ground

This is an **erroneous** fault that can be ignored.

If other vehicle faults are present, please continue troubleshooting the vehicle based on those faults.

WARRANTY INFORMATION

Not applicable.

[Copyright © 2012 BMW of North America, LLC]