

SERVICE INFORMATION BULLETIN

TITLE : Auto alarm default status

DOCUMENT # : 11 M 025


AFFECTED VEHICLES : 12C

SITUATION : Quality Engineering at McLaren Automotive have received customer reports of the alarm going off when they did not lock the vehicle. This is because the auto alarm function has been set as a default status via the instrument cluster. This function will automatically arm the alarm system if the vehicle is left unlocked with the doors and windows fully closed.


PROCEDURE : McLaren Automotive recommend that the auto alarm function be removed as a default setting.

Care point: Auto alarm function is to be disabled as in interim measure to alleviate the risk of erroneous sounding of the alarm. Customers should be informed of this adaption.


1. Move the control stalk (1) up or down (Scroll + or -) to highlight the settings menu.




2. Pull the control stalk towards you (forward) to select the settings function (2)



3. Scroll down to the vehicle option (3) in the list and pull the control stalk towards you (forward).



4. Scroll down to auto alarm and select this option by pulling the control stalk towards you (forward).
5. Ensure the auto alarm function is deactivated. In order to select this option click the OK button at the end of the control stalk.



Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.