

Service Bulletin

Circolare tecnica - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Data: 26 September 2012

Subject: **Pressure clutch disc**

Product: **F3 675 - F3 ORO**

Following the procedure of continuous product improvement the decision has been made to update the motorcycles with a new pressure clutch disc due to a possible error during assembly. It will be necessary to update the motorcycles with the following frame numbers:

- **MODEL F3 675 – F3 ORO MY 2012 up to VIN ..V001300** included

Part that must be ordered:

- N° 1 piece p/n W000W0973 PRESSURE CLUTCH DISC
- N° 1 piece p/n 8000B2615 CLUTCH COVER GASKET

Assembly procedure:

- Disassemble the clutch cover
- Disassemble the pressure clutch disc and assemble the new piece p/n W000W0973
- Assemble the clutch cover with the new clutch cover gasket
- Reassemble the motorcycle.
- Please refer to the Service Manual for any information not included in this document.
- Test the motorcycle before consignment to the customer.

This replacement is not urgent, you are kindly asked to carry out the installation of new parts during the first periodical inspection.

Procedure for Warranty reimbursement:

Send a Warranty Request for reimbursement of the parts and labor including all the relevant information regarding the motorcycle and parts with the following codes:

- Warranty Type = GS
- Special Warranty Code = 2773
- Operation Code: E999
- Labor: 0,3 ore
- Defect Code: 099

In the notes, please make reference to Service Bulletin N°98.

The reimbursement of the warranty request will be carried out via Invoice as is the normal procedure.

Thank you in advance for your collaboration.

Best Regards,
MV AGUSTA MOTOR S.p.A.
Servizio Assistenza Tecnica