

Service Bulletin

Circolare tecnica - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Data: 12 March 2012

Oggetto: **Number plate support**

Prodotto: **F3 675 - F3 ORO**

Following a continuous monitoring of product quality has been decided to update with new motorcycle license plate brackets that ensure long-term durability.

It is therefore necessary replacement on the following chassis numbers:

- **MODEL F3 675 – F3 ORO MY 2012 to a VIN ..CV000520 included**

The new license plate brackets are marked with an identification mark in the paint as shown in the picture, if it were not present proceed with replacement.



Part that must be ordered:

- N° 1 License plate bracket p/n 8000B5965 (only for Australia p/n 8A00B5965)

You are kindly asked to carry out the installation of new parts during pre-delivery operations or at the first periodical inspection.

- please refer to the Service Manual for any information not included in this document.

REIMBURSEMENT PROCEDURE:

- Send the Warranty Claim for the reimbursement of the parts and labour cost.
- Besides the complete data of the motorcycle, please indicate:
 - Type of warranty = GS
 - Number of special warranty = 2770
 - Operational code: R142
 - Labor: 0,3 hour
 - Defect code: 099
- In the notes, please make reference to Service Bulletin N°94.
- The reimbursement to the warranty request will be made via invoice.

Thank you for your co-operation; if you should require any technical support in future, we are at your service.

With best regards
MV AGUSTA MOTOR S.p.A.
Technical Service Department