



Service Bulletin

File in Section: -

Bulletin No.: PIC5730

Date: September, 2012

PRELIMINARY INFORMATION

Subject: Enabling After-blow

Models: 2013 Cadillac ATS
Condition/Concern

After-blow is a feature that dries the evaporator core by operating the blower motor after the engine is turned off. This reduces the amount of microbial growth that can create undesirable odors. The vehicle does not come equipped with the after-blow feature turned on. If the after-blow feature is required due to an odor concern, at this time the Enable feature in GDS2 is non-functional. This is due to a software concern within the HVAC module.

Recommendation/Instructions

Important: Do not replace any parts for this concern.

Engineering is currently evaluating this concern and developing a solution. This PI will be updated when additional information becomes available.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.