



# Service Bulletin

File in Section: -

Bulletin No.: PIT5120A

Date: September, 2012

## PRELIMINARY INFORMATION

**Subject:** Stabilitrak/Traction Control OFF With Red Brake Warning Lamp And DTC C0267

**Models:** 2007 - 2013 Cadillac Escalade Models  
2007 - 2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe  
2007 - 2013 GMC Sierra, Yukon and Denali Models

**This PI was superseded to update model and model years. Please discard PIT5120.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern:

Some owners may comment of a Stabilitrak off message, Traction Control off message, Service Brake System message with a Red Brake Warning Lamp and DTC C0267. There may also be complaints of the IPC going out or gauges inoperative with various modules setting low speed LAN communication DTC's. This concern may happen more at engine start up.

### Recommendation/Instructions:

This concern could be caused by an aftermarket device installed inline to the IPC connector. This device is used to recalibrate the speedometer for different size wheels/tires. Remove the aftermarket device and retest.

### Warranty Information:

Issues caused by this after-market device are not covered under warranty.

ADDITIONAL SI KEYWORDS:

U0140 U0151 U0155 U0159 U0164 U0168 U0184 U0199 U0200 U0214

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.