



Ferrari North America

Technical Information

Date: January 3, 2012
 Bulletin #: 1961
 Campaign #: 357
 Supersedes:
 Section:

Model Type: 458 Challenge
Model Year: All Models
Subject: Supplementary hydraulic fluid pipe fastener bracket

As an improvement to product reliability, it is necessary to fit the aforementioned bracket to vehicles from Assembly No. 95365 to Assembly No. 99865 as described in the following procedure. This bracket improves the fastening integrity of the hydraulic clutch fluid pipes.

The list of vehicles involved in the update is viewable at the ModisCS site using the "Recall and Service Campaign Management" function, entering the campaign number indicated as follows.

- IMPORTANT -

Those vehicles participating in an official Ferrari Challenge event must have this campaign completed prior to mandatory safety inspection at the start of each event weekend. Failure to comply could result in exclusion from the event weekend or parts thereof.


The parts to be installed are:

Fluid pipe bracket kit Part No. 70002291, consisting of (Fig. 1):


- Clutch fluid pipe fastener bracket, Part No. 276819, Qty 1 (1)
- Pillory block, Part No. 243396, Qty 1 (2)
- Pillory block plate, Part No. 243398, Qty 1 (3)
- TCE M6x45 Screw, Part No. 11568224, Qty 1 (4)
- Bush, Part No. 243399, Qty 2 (5)



Ferrari North America



The bracket part No. 276819 (1) must be fitted over the heat shield fastener bracket (6) – Fig. 2.





Ferrari North America

Service rules

The parts required to carry out the update described herein must be ordered by you directly from our Spare Parts Department in the quantities needed.

Parts Information

Quantity	Part Description	Part Number
1	Bracket Kit	70002291

Warranty Information

Component code	42.3.00.409
Labor operation	42.0.90.209.0 (1.5h)
Problem code	01
Cost code	23
Campaign #	357

Thank you for your co-operation.