

[Next Unread Message](#)**View Message****Sent on** 01 03 2012 **Expires on** 01 17 2012**From** Parts and Service Division**Subject** Product Update: 2010-11 Insight Roof Molding Loose**To:** All Honda Parts and Service Manager, Advisors and Personnel**From:** American Honda Parts and Service Division**Re:** Product Update: 2010-11 Insight Roof Molding Loose

On January 4, 2012, American Honda will announce a Product Update for some 2010-11 Insight vehicles. In certain situations, the roof molding may lift in the center allowing either the front or rear retention clips to come loose. In some cases, the molding may become damaged or detach completely from the vehicle. The product update will require application of adhesive to the roof channel to re-secure the clips in cases where the molding is still intact, and installation of updated parts in cases where the original molding is either damaged or missing.

S/B 12-001 will be posted to ISIS on January 4, 2012 in support of this product update, and will include parts, repair and warranty information related to the campaign.

As always, please make sure to check VIN status to determine if a particular vehicle is eligible for this campaign.

© 2000–2012, American Honda Motor Co., Inc. All Rights Reserved.