

SB-10043559-6305

no whistle.wav

whistle.wav

Reference SSM55577

Models Range Rover Evoque
LR2

Title Engine Whistle Re: UPS 0812

Category Engine

Last modified 28-Feb-2012 00:00:00

Symptom 497000 Engine Noise

2012MY Range Rover Evoque– VIN Range LV638042 to
LV652424 (specific vehicles) GTDi Engine Only

2012MY Freelander 2 – VIN Range LF286047 to
LF290025 (specific vehicles) GTDi Engine Only

Issue: Potential for (Freelander 2/LR2 & (Evoque) units fitted with 2.0l GTDI Petrol engine to exhibit a low speed 96th Order engine whistle.

Content

Cause: Vehicles exhibiting whistle phenomenon may suffer balance shaft gear failure leading to increased levels of NVH

Action: Listen to the attached Audio files to determine which engine requires further attention possibly resulting in an Engine change, Suspect units require an Epqr with the recordings to be attached so they can be assessed by Engineering