

**SB-10043877-8834**SI M13 02 11  
Fuel SystemsJanuary 2012  
Technical Service

---

This Service Information bulletin supersedes SI M13 02 11 **dated June 2011**.

**NEW** designates changes to this revision

**SUBJECT****TeileClearing for the Tank Ventilation Valve (Purge Valve)****MODEL**

R55, R56, R57 and R60

**NEW SITUATION**

Effective Tuesday, January 3, 2012, Part Replacement Authorization is NO longer required before replacing the Tank Ventilation Valve (Purge Valve).

From the defective parts analysis, new failure modes have been identified and put into the defect elimination process. Test plans have been improved as a result of TeileClearing on the Purge Valve. Follow the applicable test plan for the fault stored in ISTA.

We learned the following points during the Purge Valve TC action:

- Only perform a smoke test if a leak is found after performing the DMTL test plan; please refer to [SI M12 03 11](#).
- Tank Vent Valve and Charcoal Vent Valve are the same part.

Please report any errors in the test plans using the Diagnosis Feedback (envelope) icon from the top status bar (refer to [SI M07 05 06](#)).

For technical support on the Purge Valve, please submit a regular PuMA case.

Thank you for supporting this TeileClearing action.

[ MINI, a division of BMW of North America, LLC  
Copyright © 2012 BMW of North America, LLC ]