



Update Prior to Sale Notice UPS4812-1b

SERVICE BULLETIN

21-SEP-12

No.: 6-185USA

Section: GENERAL
INFORMATION

Market: USA

Jaguar Land Rover North America, LLC has identified a mis-build condition on a limited number of 2012 model year Jaguar XF vehicles.

AFFECTED VEHICLES

A total of two (2) vehicles are affected in the USA. See the attached list of affected vehicles.

DESCRIPTION OF DEFECT

Jaguar has identified a concern where the vehicles have been manufactured with incorrect torque applied to the front sub-frame fixings.

ACTION TO BE TAKEN

Jaguar retailers are to check the list of affected vehicles and must refrain from releasing these vehicles for new or used vehicle sale until further notice.

Jaguar is aware of the issue and currently in the process of developing a repair procedure. A further communication will be sent detailing the necessary action required for vehicles in retailer inventory and those vehicles that may already be in the hands of customers.

Thank you for your cooperation in this matter. Jaguar apologizes for any inconvenience this may cause.

Update Prior to Sale Notice UPS4812-1b -
Affected VIN List

RETAILER CODE / NAME	VIN
5427 - Madison Jaguar	S60303
5692 - Jaguar Wichita	S60325