



Internal notification for: G_0000153669 12106 - Safety Recall - Shift Lever Indicator May Not Display Correct Gear
gm_gmssg_q01

12/11/2012 05:36 AM

2 attachments



12106 bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 12/11/2012

Ref. number: Service / Field Action / G_0000153669

Subject: 12106 - Safety Recall - Shift Lever Indicator May Not Display Correct Gear

GM CUSTOMER CARE AND AFTERSALES
DCS2865
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 11, 2012

Subject: 12106 - Safety Recall
Shift Lever Indicator May Not Display Correct Gear

Models: 2008-2010 Chevrolet Malibu and Pontiac G6; 2007-2010 Saturn AURA with 4-Speed Automatic Transmission (ME7/MN5) and
2005-2008 Pontiac G6; 2007-2008 Saturn AURA with 4-Speed Automatic Transmission (ME7/MN5) That Were Serviced with a Suspect Replacement Shift Cable

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Safety Recall 12106 today. The total number of U.S. vehicles involved is approximately 426,000. Please see the attached bulletin for details.

Customer Letter Mailing
Letters were mailed to customers on November 9, 2012.

Global Connect (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated December 11, 2012.

Campaign Initiation Detail Report (CIDR)
The CIDR will be available December 17, 2012.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES