



Internal notification for: G_0000152787 12260 - Service Update - Buzz Noise
at Lower Right Side of Windshield - Replace Air Inlet Grille Panel
gm_gmssg_q01

12/11/2012 05:36 AM

3 attachments



12260 bulletin.pdf



12260 Inventory VINs.xls



GM Style Sheet.css

Your email client does not support HTML messages

Date: 12/11/2012

Ref. number: Service / Field Action / G_0000152787

Subject 12260 - Service Update - Buzz Noise at Lower Right Side of Windshield - Replace Air Inlet Grille
: Panel

GM CUSTOMER CARE AND AFTERSALES
DCS2861
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 11, 2012

Subject: 12260 - Service Update Bulletin
Buzz Noise at Lower Right Side of Windshield - Replace Air Inlet
Grille Panel

Models: 2012-13 Chevrolet Corvette

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Service Update Bulletin 12260 today. The total number of U.S. vehicles involved is approximately 7,500. Please see the attached bulletin for details.

Global Warranty Management (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated December 11, 2012. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link
The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):



12260 bulletin.pdf Acrobat PDF (162.4KB)

12260 bulletin



12260 Inventory VINs.xls Microsoft Office Excel Worksheet 8.0-2003 (Windows) (190.5KB)