

Thomas Built Buses, Inc.

To: LIVE OAK USD
From: Tracy Sauerbrey
Subject: VON 81 HDX Heater/Defroster 3 Fuses Replacement
Date: January 2013

Dear Thomas Customer:

Our records indicate that you purchased the following unit(s) listed below. Thomas has determined that the fuse(s) for the heater/defroster is the incorrect size and needs to be replaced.

We strongly recommend that you perform the necessary repair work to your unit(s). Please contact your local Thomas dealer to arrange for the repairs to be made. You can find your local Thomas dealer at www.thomasbus.com.

<i>Order#</i>	<i>Chassis#</i>	<i>Body#</i>	<i>Vin</i>
21821	84967	930090	1T7YU4E28A1121821

Total Units : 1

SAMPLE