



# Tech Tips

TT 94-13-01

Date: May 24, 2013

## 2009-2010 Passat, 2009-2013 CC – Cruise Control Inoperative, Fault B115411 “Cruise Control Switch Short Circuit to Ground” after J527 Steering Column Control Module Replacement

When replacing J527 steering column control module, be aware that there may be two different replacement part numbers listed in ETKA. The correct replacement part number is determined by the hardware part number of the module *originally* installed in the vehicle.

If fault B115411 “Cruise Control Switch Short Circuit to Ground” is stored in new J527, and/or the cruise control is inoperative after module replacement, verify that the replacement module part number matches the part number of module installed during factory assembly. If necessary, consult GFF paperless to determine original control module hardware part number.