



Tech Tips

TT 00-07-89

Date: 2007

2006-2009 Beetle, Beetle Convertible Equipped with 2.5L Engine – Malfunction During Software Update with "\$33\$10" Displayed

May 17, 2013: Update to Model Applicability.

If you encounter a malfunction message "\$33\$10" while performing a software update, try removing pin 6 from the Data Link Connector (DLC) and attempt the software update with the pin removed. Be sure to reinstall the pin before the vehicle leaves the shop.