

Reference SSM62797

Models LR4 / L319
Range Rover Sport / L320

Title GEN2.1 Audio Compact Disc Player Issues

Category Electrical

Last modified 31-Jan-2013 00:00:00

Symptom 207000 Entertainment Systems

Issue: A customer may report a permanent or intermittent concern that the Audio Compact Disc Player will not allow a CD to be ejected/ loaded or the CD will display 'stuck'.

Cause: Currently under analysis, however a reconfiguration of the Audio Front Control Module appears to rectify the

Content concern.

Action: Please submit an ePQR for any Discovery 4/LR4 and Range Rover Sport 2012 to 2013 MY only, where the concern is identified, detailing the exact vehicle symptoms that the customer has reported and the repair that was carried out to rectify the concern.