

Right Hand strut mount.jpg

Reference	SSM67377
Models	Range Rover Sport / L494
Title	L494 Range Rover Sport - Visual Appearance of Front Suspension Body Mounts
Category	Body
Last modified	30-Jul-2013 00:00:00
Symptom	111000 Body Panel(s)/Unibody
Content	<p><u>Issue</u> On L494 Range Rover Sport reports that the Right Hand Underbonnet Front Suspension Body Mount differs in visual external appearance compared to the left hand side.</p>
	<p><u>Cause</u> The Right Hand side has a less smooth finish compared to the left hand Side, this is simply a cosmetic issue and the Integrity of the Suspension Body Mount is not affected.</p>
	<p><u>Action:</u> No repair or replacement is necessary, this communication is for information only and the Suspension Body Mount meets JLR Engineering standards. A photograph of the Right hand Front Suspension Body Mount is attached for identification.</p>

