

Air Splitter sealing / air tightness with passenger floor

POSSIBLE AIR RETURN BETWEEN EVAP AIR CONDUIT AND COMPARTMENT.

NO AIRTIGHTNESS BETWEEN DUCT AND FLOOR / FLOOR STRUCTURE

ALL X SERIES VEHICLES WITH LARGE A/C ARE INCLUDED.

FROM EVAPORATOR COMPARTMENT ADD A SIKA SEALANT JOINT #680532 BETWEEN DUCT AND STRUCTURE AND BETWEEN DUCT AND FLOOR.

TO AVOID REMOVING THE AIR FLOW SPLITTER, SEALING CAN BE PERFORMED FROM EVAPORATOR COMPARTMENT.



