



Service Bulletin

PRELIMINARY INFORMATION

Subject: IPC Not Showing Radio Or Phone Data Audio Off Message Displayed IPC May Change From Touring To Sport Display And Right Steering Wheel Control Inoperative Intermittently

Models: 2014 Buick Lacrosse built before 12/19/2013
2014 Buick Regal built before 1/21/2014

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment the IPC is not showing radio or phone data, Audio Off message is displayed, and the Right Steering Wheel Control is inoperative. They may indicate the IPC intermittently switches to "Sport" display and other cluster personalization features return to factory default.

This may be the result of a reset condition within the IPC.

Recommendation/Instructions

New IPC software has been created to address these concerns. Using TIS2WEB, please update the IPC calibrations and reevaluate.

Note: This update only applies to vehicles built before the dates listed above if audio is still present, radio controls still function, and no current infotainment codes are set.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

ADDITIONAL SI KEYWORDS:

mode

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION