



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Paint Code Used To Refinish The Underside Of The Rear Hatch Or Decklid

Models: 2005 - 2014 Chevrolet Corvette

This PI was superseded to add 2008-14 model years. Please discard PIC4299.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some Body Shop Technicians may comment that they cannot locate the "Low Gloss" paint code that is used to paint the underside / interior of a rear hatch or decklid.

Recommendation/Instructions

Use paint code WA167A to paint these areas.

Warranty Information

There is not a labor time or labor operation associated with this PI because the labor time is considered part of the original repair.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION