



Service Bulletin


PRELIMINARY INFORMATION

Subject: Identification and Location of the Transmission Control Module (TCM) and the Engine Control Module (ECM)

Models: 2014 Chevrolet Spark
Equipped with Continuously Variable Transmission (CVT) (RPO M4M)


The purpose of this PI is to help the Service Department personnel become familiar with the identification and location of the transmission control module (TCM) and the engine control module (ECM).

Transmission Control Module



The TCM is located in the vehicle under the left side of the instrument panel (2) as shown in the illustration above.

Engine Control Module



The ECM is located under the hood behind the battery with a label marked CVT as shown in the illustration above.

Note: The purpose of the label is an aid in the vehicle assembly plant.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION